	Approved For Release 2002/08/20 : CIA-RDP78B04747A002700030005-5	
+ .		STAT
	January 20, 1965	STAT
· . [
	Subject: Recommended Spares for the Machine for Immediate Support	STAT
	Gentlemen,	STAT
· ·	As requested in recent conversations has reviewed the recommended spare parts list. As a result of this review, it is herein recommended that the customer procure the following items for immediate support in the instrument.	STAT STAT STAT
	A) A quantity of two (2) Lamp Housings, drawing #701231	STAT STAT
	B) A quantity of three (3) Photo Multipliers, drawing #106358 C) A quantity of two (2) Pumps, drawing #107406	STAT STAT
	The prices are as listed in the recommended spare parts list, document dated September 1964.	STAT STAT
	the per unit price to cover costs of procurement, handling, etc. When the customer has a sufficient quantity of the Lemp Housings, it wis be possible for him to send the spare Lemp Housing for replament of the lamp and coil and realignment instead of purchasing additional Lamburgs. If there are any question in relation to this matter, please contact	STAT
Teste; Thisre	as Junished in January very cruly yours.	STAT
This hasnot	veen accompained so	STAT STAT
•		STAT
V	Approved For Release 2002/08/20 : CIA-RDP78B04747A002700030005-5	